

NPWT Irreparable Air Leak / Device Failure: Alternate Dressing – Take Down

(Click on the title to access the video)

This 1:50-minute video demonstrates how to manage a Negative Pressure Wound Therapy (NPWT) dressing in the event of an irreparable leak or machine/device failure by taking down the dressing. Please note the video may take 1-2 minutes to download.

The video has been developed by the British Columbia Provincial Nursing Skin & Wound Committee and is posted on CLWK for your personal development; you can review it as often as you wish.

The CLWK site does not provide certificates of completion; if you need to have a record that you have watch this video, please access the video through the British Columbia LearningHub site or the Yukon Learning Management System site.